


21 Measurement gauge



Balance [1]



Hear hygrometer with thermometer [1]



Maximum minimum thermometer [1]



Fare and rain meter (around 1925) [1]



Portable magnetic compass [1]



Pedometer (1930!' s USA) [1]

The weather is visible in the left glass tube.
The liquid inside crystalize depending on the weather.



Proportional compass [1]



Planimeter (measurement of area)

{1} Donation by Emeritus Prof. Yakichi Higo of Tokyo Institute of Technology